

TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R189X - HIGH QUEST LIGHTWEIGHT STOWABLE JACKET

24.02.2016

	XS	S	M	L	XL	2XL	3XL
Full chest in inches*	34	38	40	42	44	47	49
Full chest in cm*	86,36	96,52	101,6	106,68	111,76	119,38	124,46
German clothing size (men)	44	48	50	52	54	56	58

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm